



(March 21) 50 (4) Examined 900 (900 corner and 101 107 205 corner) for foundation deposits of none were found.



- (5) Bldg 500 A continued clearing ^{stone} pavement
 (6) Bldg 100



see next page